

# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18<sup>TH</sup> STREET- SUITE 300
DENVER, CO 80202-2466
Phone 800-227-8917
http://www.epa.gov/region08



Ref: 8EPR-SR

April 21, 2006

OLIVIA A MARTINEZ 3317 CURTIS ST DENVER, CO 80205

RE: 3317 CURTIS ST

Dear Owner,

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: 3317 CURTIS ST	EPA Cleanup Levels
Lead	
273 parts per million (ppm)	above 400 ppm
Arsenic	
4 ppm	above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely,

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8

## Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-3317-CU-01 Client Project ID: 213001.01 Date Collected: 4/5/06

Date Received:

4/5/06 4/6/06 Lab Work Order: 06-2212 Lab Sample ID: 06-2212-01

Sample Matrix: Soil

**METALS** 

Method: SW6010 Prep Method: SW3050

Dilution Factor: 1 Date Prepared: 4/18/06 Lab File ID: 041906pm Method Blank: MB-9723 Date Analyzed: 4/20/06 Lab Fraction ID: 06-2212-01A Analytes CAS Number Result LQL Units Arsenic 7440-38-2 4.3 4.0 mg/Kg 7439-92-1 5.9 Lead 380 mg/Kg

Analyst

11/1C

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\*-Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

#### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-3317-CU-02 Client Project ID: 213001.01

4/5/06

4/6/06

Lab Work Order: 06-2212 Lab Sample 1D: 06-2212-02

Date Collected:

Date Received:

Sample Matrix: Soil

**METALS** 

Method: SW6010 Prep Method: SW3050

Date Prepared:4/18/06Lab File ID:041906pmDilution Factor:1Date Analyzed:4/20/06Method Blank:MB-9723Lab Fraction ID:06-2212-02AAnalytesCAS NumberResultLQLUnits

Arsenic 7440-38-2 U 4.1 mg/Kg Lead 7439-92-1 150 6.0 mg/Kg

> MB Analyst

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\*-Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 4/20/06

### Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample 1D: VB-3317-CU-03 Client Project ID: 213001.01 Date Collected: 4/5/06

Lab Work Order: 06-2212 Lab Sample 1D: 06-2212-03

Sample Matrix:

290

Soil

5.9

mg/Kg

Date Received: 4/6/06

Lead

Method: SW6010	METALS Prep Method: SW3050			
Date Prepared: 4/18/06	Lab File 1D: 041906pm	Dilu	ition Factor: 1	
Date Analyzed: 4/20/06	Method Blank: MB-9723	Lab	Fraction ID: 06-2	212-03A
Analytes	CAS Number	Result	LQL	Units
Arsenic	7440-38-2	4.4	4.0	mg/Kg

7439-92-1

Analyst

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 4/20/06

3317 CURTIS

prop ID 7017

4	口
A DOG TO A	Δ
<b>1</b> 1	. д
Storage N	
	_

	Sections	SA UP	F(2.35
	-	33	5
1	2	44	7
		122	18

VB 3317 C U 01 - 1395 VB 3317 C U 02 - 1396 VB 3317 C U 03 5 1395

140'

	3317 Curtis	
<u> </u>	*	A
*	<u> </u>	4 *
*	Otter	A

Curtis street

1 # 7017 4/5/06 MV TNB



ن جيري

#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
Victor Ketellapper
Phone 800-227-8917
http://www.epa.gov/region08

#### CONSENT FOR ACCESS TO PROPERTY

Name: Olivia A Martinez (or current property owner)

Location of Property: 3317 Curtis St

Property ID: 7017

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having continued access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfund), 42 U.S.C. § 9601 et seq.

Drinted Name

303-296-1601

Phone Number

Signature

Date<sup>7</sup>